


CHARGING INSTRUCTIONS

Step 1: To charge the battery, insert the transformer that came with your display product into the battery. Plug transformer into an outlet and charge for several hours.



GREEN LIGHT: A green light on the transformer will indicate when the battery is fully charged. Remove transformer from battery.



LITHIUM ION BATTERY

Step 2: Insert one end of the small plug into the battery and one end into the display or counter.



NOTE: It is recommended to have two batteries per product to allow charging of one battery while the other battery is in use.

