


# CHARGING INSTRUCTIONS

**Step 1:** To charge the battery, insert the transformer that came with your display product into the battery. Plug transformer into an outlet and charge for several hours.




**GREEN LIGHT:** A green light on the transformer will indicate when the battery is fully charged. Remove transformer from battery.



# LITHIUM ION BATTERY

**Step 2:** Insert one end of the small plug into the battery and one end into the display or counter.



**NOTE:** It is recommended to have two batteries per product to allow charging of one battery while the other battery is in use.

