


## Product Parts

- 1 - Left Vertical Shock-Corded Pole
- 2 - Right Vertical Shock-Corded Pole
- 3 - Center Vertical Shock-Corded Pole
- 4 - Horizontal Stabilizer Poles (x4)
- 5 - 3-Way Corner Connectors (x2)
- 6 - 2-Way Corner Connectors (x2)
- 7 - Graphic




## Display Set-Up

### Step 1


Assemble the Corner starting with the Left and Right Vertical Shock-Corded Poles (1 & 2). Connect the 3-Way Corner Connectors (5) to the top and bottom of the Center Vertical Shock-Corded Pole (3). Connect the 2-Way Corner Connectors to the bottom of both left and right Vertical Shock-Corded Poles (1 & 2). Connect everything else together with the Horizontal Stabilizer Poles (4).

See detailed layout below.



### Step 2

Slide the Graphic down over the top of the hardware.



### Step 3

Zip the Graphic (7) closed.

## Storage & Care

Store in a cool dry location. Machine wash cold, gentle cycle. Tumble dry no heat.