

**Step 1.** Attach cross bar to round legs, tighten using a 5mm hex key.

**Step 2.** Attach counter to cross bar using 2" long  $\frac{1}{4}$ "-20 button head screws, tighten using  $\frac{5}{32}$ " (4mm) hex key.

